

HSENI CONSTRUCTION GROUP STATISTICS


01 APR 2017 – 30 JUN 2017


| | fatalities | Major injuries (MI) | MI on | MI on | Over 3 day | 3 day on private | 3 day on | Dangerous |
|----------------|------------|---------------------|--------------|-------------|------------|------------------|-------------|------------|
| | | | private site | public site | | site | public site | occurrence |
| Total | | 19 | | | 39 | | | 7 |
| numbers | | | | | | | | |
| Comparison | | | 14 | 5 | | 29 | 10 | |
| private/public | | | | | | | | |


TABLE 1: numbers of reported incidents (including major injuries by type)











| Date | Major | Fatals | Over 3 day | Public | Private | Injury (type) | Occupation | Comments |
|-----------|-----------|--------|------------|--------|---------|------------------|--------------|--|
| 03/04/201 | Fall | | | Υ | | Fracture (ankle) | Construction | Fall under 2ms- lost balance when going down stairs and fell |
| 7 | | | | | | | | |
| 06/04/201 | Slip/Trip | | | | Υ | Fracture (Foot) | Joiner | Went over on ankle |
| 7 | | | | | | | | |
| 11/04/201 | Struck by | | | | Υ | Head injury | Construction | Door frame fell on IP head |
| 7 | | | | | | | | |
| 11/04/201 | Manual | | | | Υ | Fracture (Wrist) | Other | Fell while carrying a load |
| 7 | Handling | | | | | | | |
| 11/04/201 | Trapped | | | | Υ | Fracture (hand) | Construction | IP hand got trapped when load they were shifting became unsteady |
| 7 | | | | | | | | |

| 11/04/201 7 | Struck by | | | Υ | Fracture (face) | Construction | Struck by 8.5 steel rafter |
|----------------|-----------|--------------------|---|---|-----------------------|--------------|--|
| 13/04/201 7 | Fall | | Y | | Fracture (hand) | Plumber | Fall under 2ms - slipped while getting out of van |
| 25/04/201 7 | Fall | | | Y | Fracture (Upper Limb) | Scaffolder | Fall over 2ms - fell from scaffold |
| 27/04/201 7 | Struck by | | | Y | Fracture (Lower Limb) | Construction | Struck by concrete mould crushing IP leg |
| 28/04/201 | Contact | | | Y | Fracture (hand) | Joiner | Contact with machine caught his hand |
| 28/04/201 7 | Fall | | | Υ | Fracture (foot) | Construction | Fall under 2ms - fell from ladder |
| 04/05/201 7 | Slip/Trip | | Y | | Fracture (foot) | Joiner | Stepped on uneven group when getting out of van and went over on ankle |
| 23/05/201 7 | Fall | | Υ | | Fracture (trunk) | Technician | Fall under 2ms - Fell from stepladder |
| 24/05/201 | Struck by | | | Y | Fracture (head) | Labourer | Struck by piece of scaffold |
| 14/06/201 | Exposure | | | Υ | Burns - Face | Labourer | Burned from flames coming from back of tar hot box |
| 15/06/201 | Fall | | | Υ | Fracture (ankle) | Bricklayer | Fall over 2ms - fell from 3m ladder |
| 22/06/201 | Struck by | | Y | | Fracture (foot) | Other | Struck by manitou which ran over IP foot |
| 28/06/201 7 | Fall | | | Y | Fracture (Wrist) | Engineer | Fall under 2ms - IP fell from ladder |
| 30/04/201 | Fall | | | Y | Fracture (ankle) | Construction | Fall over 2ms - fell from ladder |
| 04/04/201 | | Struck by | | Y | Injury to lower limb | Construction | IP working on a line drainage struck on leg by falling clay |
| 04/04/201 | | Manual Handling | | Υ | Strained back | Joiner | Hurt back while lifting generator |
| 10/04/201 | | Struck by | Y | | Lacerations hand | Construction | Bar from skip dislodged and struck IP on hand |
| 11/04/201 | | Struck by | | Y | Lacerations face | Joiner | Ladder fell from van hitting IP on face |
| 12/04/201 | | Manual Handling | | Y | Lacerations finger | Plumber | Removing sink which broke and cut IP finger |
| 20/04/201 7 | | Contact | Υ | | Superficial injuries | Construction | IP came in contact with mini digger bucket |
| 20/04/201 | | Manual Handling | | Y | Strained back | Engineer | Injured back while lifting fire extinguisher |
| 21/04/201 7 | | Slip/trip | | Υ | Contusion - Trunk | Bricklayer | IP slipped on scaffolding and fell back on wall |

| Manual | | Υ | Strained back | Joiner | Hurt back while moving sofa |
|--------------------|--|--|--|---|--|
| Handling | | | | | |
| Slip/trip | Y | | Strained ankle | Other | Fell on uneven surface |
| Manual | | Υ | Strained upper limb | Engineer | Hurt arm while pushing spiral duct through ceiling |
| | | | | | |
| Slip/trip | | Y | Strained ankle | Construction | Slipped on stone and went over on ankle |
| Slip/trip | | Υ | Superficial injuries - ankle | Construction | Slipped while pulling a pallet truck |
| Manual Handling | | Υ | Strained - lower limb | Welder | Working on his haunches and twisted his knee as he got up |
| Fall | | Υ | Contusion - Upper limb | Other | Fall under 2ms fell over chains |
| Struck by | Y | | Lacerations finger | Construction | Metal stud fell and struck IP on hand cutting finger |
| Manual Handling | | Υ | Strained back | Driver | Hurt back while using hand shovel |
| Fall | | Υ | Strained ankle | Other | Fall under 2ms - fell from ladder |
| Manual Handling | | Υ | Lacerations hand | Other | Cutting high cables with stanley knife accidentally cut hand |
| Manual Handling | | Υ | Strained trunk | Joiner | Twisted shoulder while carrying load |
| Slip/trip | | Υ | Strained ankle | painter | Slipped on ground fell back into uncovered chamber - hurt ankle |
| Manual Handling | | Υ | Strained upper limb | Construction | Hurt upper arm while lifting fork extenders |
| Struck by | | Υ | Concuss - head injury | Other | Struck by pipe on head |
| Slip/trip | | Y | Injured trunk | Construction | Slipped on glass |
| Slip/trip | | Υ | Superficial injury - ankle | Fitter | Stepped on nail |
| Manual Handling | Y | | Head injury | Construction | Carrying load and hit head on scaffold |
| Contact | | Υ | Dislocated - foot | Builder | Contact with machine trapping foot |
| Struck by | | Υ | Strained ankle | Construction | Pallet truck failed and struck IP trapping foot |
| Struck by | Υ | | Contusion head | Construction | Struck by traffic lamp on head |
| Fall | | Υ | Strained foot | Plasterer | Fall under 2ms - fell into uncovered manhole |
| | Handling Slip/trip Manual Handling Slip/trip Slip/trip Manual Handling Fall Struck by Manual Handling Fall Manual Handling Slip/trip Manual Handling Slip/trip Slip/trip Manual Handling Slip/trip Manual Handling Struck by Slip/trip Slip/trip | Handling Slip/trip Manual Handling Slip/trip Manual Handling Fall Struck by Y Manual Handling Fall Manual Handling Fall Manual Handling Manual Handling Slip/trip Manual Handling Slip/trip Manual Handling Struck by Slip/trip Slip/trip | Handling Slip/trip Y Manual Handling Slip/trip Y Slip/trip Y Manual Handling Fall Y Manual Handling Fall Y Manual Handling Fall Y Manual Handling Manual Handling Slip/trip Y Manual Handling Slip/trip Y Manual Handling Slip/trip Y Manual Handling Slip/trip Y Manual Handling Struck by Y Slip/trip Y Struck by Y | Handling Slip/trip Y Strained ankle Manual Handling Slip/trip Y Strained upper limb Slip/trip Y Strained ankle Slip/trip Y Superficial injuries - ankle Manual Handling Fall Y Contusion - Upper limb Struck by Y Lacerations finger Manual Handling Fall Y Strained ankle Y Strained ankle Manual Handling Manual Handling Manual Handling Manual Handling Slip/trip Y Strained ankle Manual Handling Slip/trip Y Strained upper limb Arandling Struck by Y Concuss - head injury Slip/trip Y Superficial injury - ankle Manual Handling Contact Y Dislocated - foot Struck by Y Contusion head | Handling Slip/trip Y Strained ankle Other Manual Handling Slip/trip Y Strained upper limb Engineer Construction Slip/trip Y Superficial injuries - ankle Welder Handling Fall Y Contusion - Upper limb Other Struck by Y Lacerations finger Construction Manual Handling Fall Y Strained ankle Other Struck by Y Lacerations finger Construction Manual Handling Fall Y Strained ankle Other Manual Handling Manual Handling Manual Handling Y Strained trunk Joiner Manual Handling Slip/trip Y Strained ankle Driver Manual Handling Manual Handling Slip/trip Y Strained ankle Driver Construction Context Total T |

| 12/06/201 7 | | | Manual Handling | | Υ | Fracture (finger) | Construction | Erecting security fencing and caught his finger |
|----------------|----|---|--------------------|----|----|---------------------------|---------------|--|
| 13/06/201 | | | Slip/trip | Y | | Strained lower limb | Other | Fell down uncovered manhole |
| 15/06/201 7 | | F | all | Υ | | Strained ankle | Fitter | Fall under 2ms fell on stairs |
| 16/06/201 | | C | Contact | | Y | Lacerations lower limb | Scaffolder | Contact with stihl saw cut his knee |
| 21/06/201 | | S | Slip/trip | | Υ | Strained ankle | Other | Slipped on man hole cover and fell into hole |
| 21/06/201 | | (| Contact | | У | Hurt finger | Fitter | Contact with Poultry feedline auger caught his finger |
| 22/06/201 | | F | all | Y | | Contusion trunk | Steel Erector | Fall under 2ms - fell from ladder |
| 24/06/201 7 | | | Manual Handling | | Y | Superficial injury finger | Construction | Lifting piece of timber cut his finger |
| 29/06/201 7 | | | Slip/trip | Y | | Multiple strains | Other | Jumped from van and slipped hurting his knee and other parts |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Totals | 19 | 3 | 39 | 15 | 43 | | | |
| | | | | | | | | |
| | | | | | | | | |