

HSENI CONSTRUCTION GROUP STATISTICS

01 JUL 2017 - 30 SEPT 2017





Date	Major	Fatals	Over 3 day	Public	Private	Injury (type)	Occupation	Comments
04/07/2017	Slip/Trip				Y	Fracture (ankle)	Construction	Slipped on wet scaffold boards
04/07/2017	Fall				Y	Fracture (Lower limb)	Joiner	Fall under 2ms - fell from frame of peri shutter
06/07/2017	Fall				Y	Multiple fractures	Technician	Fall under 2ms - fell between roof joists
14/07/2017	Fall				Y	Fracture (foot)	Bricklayer	Fall over 2ms - fell from scaffold cage
25/07/2017	Struck by				Y	Dislocation (lower limb)	Joiner	Struck by falling timber framed panels
28/07/2017	Fall				Y	Fracture (upper limb)	Joiner	Fall over 2ms - fell from lift shaft
02/08/2017	Overturn				Y	Fracture (upper limb)	Driver	Telehandler overturned when raising tipping skip
04/08/2017	Struck by			Y		Fracture (lower limb)	Construction	IP thrown from dumper truck which then rolled back on his leg
08/08/2017	Trapped				Y	Fracture (ankle)	Bricklayer	IP trapped by slabs collapsing
09/08/2017	Fall				Y	Fracture (ankle)	Construction	Fall under 2ms- fell from wall
11/08/2017	Fall				Y	Fracture (lower limb)	Bricklayer	Fall under 2ms - fell from broken scaffold plank
14/08/2017	Fall			Y		Multiple fractures	Labourer	Fall over 2ms - fell from milling machine
16/08/2017	Manual Handling				Y	Fracture (upper limb)	Engineer	Injured while using a hand held drill when bit got caught
17/08/2017	Fall				Y	Fracture (wrist)	Plumber	Fall under 2ms - fell from stepladders
25/08/2017	Fall				Y	Fracture (upper limb)	Roofer	Fall over 2ms - fell from ladder
25/08/2017	Fall				Y	Fracture (wrist)	Construction	Fall under 2ms - fell from 3rd run of ladders
06/09/2017	Struck by				Y	Fracture (lower limb)	Joiner	Struck by shutter
06/09/2017	Fall				Y	Fracture (wrist)	Construction	Fall under 2ms - fell from stepladder
18/09/2017	Fall				Y	Fracture (ankle)	Construction	Fall over 2ms - fell from roof
19/09/2017	Fall				Y	Fracture (trunk)	Engineer	Fall over 2ms - fell from wall
20/09/2017	Struck by				Y	Eye injury	Engineer	IP hit in eye by debris was not wearing eye protection
20/09/2017	Fall				Y	Fracture (upper limb)	Plasterer	Fall under 2ms - fell off plank on stairwell
22/09/2017	Fall				Y	Fracture (lower limb)	Drivers Mate	Fall under 2ms - IP lost footing while disembarking trailer
25/09/2017	Fall				Y	Fracture (ankle)	Bricklayer	Fall under 2ms - fell from scaffold
04/07/2017			Manual Handling		Y	Fracture (upper limb)	Construction	Fell while carrying a slab
20/04/2017			Electric contact	Y		Hand injury	Electrician	IP grabbed live cable
19/07/2017			Fall		Y	Laceration (face)	Construction	Fall under 2ms - fell from ladder
19/07/2017			Fall		Y	Laceration (head)	Joiner	Fall over 2ms - fell from wall

25/07/2017	Fall		Y	Superficial injuries	Joiner	Fall under 2ms - fell from scaffold
25/07/2017	Manual Handling		Y	Fracture (finger)	Driver	IP caught finger when helping to move concrete ring
25/07/2017	Manual Handling		Y	Laceration (hand)	Construction	Caught top of finger when lifting front wheel barrow
28/07/2017	Struck by	Y		Multiple injuries	Engineer	Struck by vehicle
28/07/2017	Manual Handling		Y	Strained (trunk)	Construction	IP injured himself when tightening a bolt
31/07/2017	Machinery contact		Y	Ankle injury	Construction	Contact with saw
31/07/2017	Manual Handling		Y	Several lacerations	Operative	Injured when removing strapping from windows
01/08/2017	Fire exposure		Y	Burns Multiple	Construction	IP trousers caught fire when stilh saw spark hit paint
04/08/2017	Manual Handling		Y	Strained (back)	Other	Injured when lifting boiler into van
07/08/2017	Manual Handling		Y	Upper limb injury	Operative	Injured when lifting
09/08/2017	Slip/trip	Y		Fracture (finger)	Office Manager	IP visited site to fix laptop tripped over manhole on way out
12/08/2017	Manual Handling		Y	Strained (back)	Sheet metal worker	Injured back when lifting
17/08/2017	Slip/trip		Y	Strain (lower limb)	Bricklayer	Slipped on steps
17/08/2017	Slip/trip		Y	Lower limb injuries	Construction	Injured while pushing chute of skip
20/08/2017	Machinery contact		Y	Fracture (finger)	Construction	Cut finger on machine
23/08/2017	Manual Handling		Y	Head injuries	Construction	Injured when pulling lead through dark area
23/08/2017	Fall	Y		Multiple strains	Welder	Fall under 2ms
30/07/2017	Slip/trip	Y		Strained (ankle)	Plumber	Tripped on uneven ground
04/09/2017	Struck by		Y	Superificial injuries	Other	Struck by skip
04/09/2017	Manual Handling	Y		Strained (back)	Engineer	Injured when carrying equipment
07/09/2017	Manual Handling		Y	Strained (back)	Surveyor	Injured when entering confined space
09/09/2017	Struck by	Y		Lower limb injuries	Construction	Struck by tree
13/09/2017	Fall		Y	Injury to side	Construction	Fall under 2ms
13/09/2017	Fall		Y	Contusion to back	Other	Fall under 2ms - broken scaffold board
15/09/2017	Manual Handling	Y		Strained (back)	Scaffolder	Twisted back when lifting scaffold pole
19/09/2017	Fall		Y	Laceration (trunk)	Construction	Fall over 2ms - fell from scaffold
21/09/2017	Slip/trip	Y		Laceration (lower limb)	Construction	IP slipped on decking
21/09/2017	Contact		Y	Contusion (foot)	Driver	Block slipped from stack hitting IP
25/09/2017	Manual Handling	Y		Laceration (wrist)	Construction	Window broke when IP closed it
27/09/2017	Manual Handling	Y		Strained (trunk)	Labourer	Injured when climbing over a wall
28/09/2017	Contact	Y		Eye injury	Labourer	Shovel blade in contact with IP eye