

## **HSENI CONSTRUCTION GROUP STATISTICS**


01 January 2016 – 31 March 2016


	fatalities	Major injuries (MI)	MI on	MI on	Over 3 day	3 day on private	3 day on	Dangerous
			private site	public site		site	public site	occurrence
Total	1	23			32			4
numbers								
Comparison			15	8		22	10	
private/public								


TABLE 1: numbers of reported incidents (including major injuries by type)











Date	Major	Fatals	Over 3 day	Public	Private	Injury (type)	Occupation	Comments		
30/03/20 16		1		Υ		Fall	NIHE Resident	Fell into excavation		
04/01/20 16	Fall			Υ		Fracture-Upper limb	Plumber	Fall under 2ms- fell when descending from podium steps		
07/01/20 16	Struck				Υ	Fracture-Hand	Environmenta I	Got hand trapped in an attic door		
19/01/20 16	Trapped				Υ	Fracture-Ankle	Construction	ankle trapped by davit		
26/01/20 16	Struck				Υ	Fracture-Lower limb	Lorry Driver	IP got leg trapped between units when delivering units on site		
27/01/20 16	Struck			Υ		Fracture-jaw	Plant Driver	street lighting column struck IP on face		
03/02/20 16	Slip				Υ	Fracture-Wrist	Construction	Slipped on botton run od ladder		
04/02/20 16	Trip				Υ	Fracture-Upper limb	Plant Driver	Tripped on loose ground		
12/02/20 16	Struck			Υ		Dislocation-Lower limb	Fitter	pole fell on IP leg dislocating knee cap		
19/02/20 16	Fall				Υ	Fracture-Face	Builder	Fall under 2ms - slipped grabbed fence which fell on top of him		
22/02/20 16	Fall				Υ	Fracture-Wrist	Construction	Fall over 2ms- Ladder slipped while IP working on them		
24/02/20 16	Struck				Υ	Fracture-Foot	Construction	No details		
24/02/20 16	Fall			Υ		Fracture-Wrist	Construction	Fall under 2ms-fell from safety steps		
25/02/20 16	Fall				Y	Fracture-Trunk	Fitter	Fall under 2ms-fell back from steps when loose timber hit him		
26/02/20 16	Fall			Υ		Fracture-Back	Electrician	Fall over 2ms-Fell from ladder while working on street lighting		
29/02/20 16	Struck				Υ	Fracture-Foot	Construction	No details		
01/03/20 16	Struck				Y	Fracture-Wrist	Other	Struck by Forklift		
01/03/20 16	Fall				Υ	Fracture-Upper limb	Bricklayer	Fall under 2ms - scaffold board collapsed IP fell		
05/03/20 16	Fall			Υ		Fracture-Trunk	Other	Fall under 2ms - IP lost footing slipped down grassy bank		
08/03/20 16	Slip			Υ		Dislocation-Upper limb	Bricklayer	Slipped on loose ground		

11/03/20 16	Slip			Υ	Fracture-Wrist	Fitter	Lost footing and slipped
18/03/20	Struck			Υ	Lower limb injury	Construction	No details
16							
24/03/20	Fall		Υ		Fracture-Wrist	Plumber	Fall under 2ms-fell from ladder
16							
24/03/20	Fall			Υ	Fracture-Upper limb	Bricklayer	Fall under 2ms - IP fell out of lorry
16							·
06/01/20		Exposure		Υ	Eye injury	Joiner	Dust got into IP eye while planing door
16							
08/01/20		Manual Handling		Υ	Strain - Ankle	Engineer	Went over on ankle over on ankle while carrying
16							, -
09/01/20		Fall		Υ	Strain - Back	Construction	Fall under 2ms - tripped on tool lead
16							
13/01/20		Trip	Υ		Strain - Lower limb	Fitter	twisted knee when stepping down
16		"					a state of the grade
15/01/20		Slip		Υ	Strain - Ankle	Builder	Slipped on ice went over on ankle
16							3.77
19/01/20		Manual Handling	Υ		Superficial injury - fingers	Plumber	Trapped fingers while carrying boiler
16					- Supermonar myar y milgers		Trapped images trime earlying some.
25/01/20		Struck		Υ	Laceration - Lower limb	Plasterer	Went through manhole cover
16		Struck		'	Laceration Lower initia	i iusterer	Welle through mannere cover
27/01/20		Trip		Υ	Fracture - Foot	Other	caught foot on back wheel when jumping from forklift
16		'''		,	1.14014110 1.001		Save and a save and a save and a save
28/01/20		Struck		Υ	Injury - Foot	Construction	telehandler struck IP on foot
16		Struck		'	linguity 1 cost	Construction	teremander struck in on root
30/01/20		Fall		Υ	Contusion - Back	Engineer	Fall over 2ms - lost balance fell from roof of plant room
16				,		2.18.1.22.	
02/02/20		Fall	Υ		Fracture - Upper limb	Engineer	Fall under 2ms - fell from stepladders
16					Tractare Opper mile	Liigineei	Tall allact 21115 Tell Holli Stepladaels
03/02/20		Manual Handling		Υ	Strain- Back	Builder	IP felt pain in back when carrying bags of sand
16		I Wanda Hanamig		'	Jerum Buen	Bullaci	in tele pain in back when earlying bags of saina
05/02/20		Struck		Υ	Strain - Lower limb	Construction	trapped when wall fell on IP
16		Struck		'	Strain Lower mile	Construction	trupped when wan fell on h
05/02/20		Struck	Υ	+	Injury - face	Engineer	Struck on face by barrier
16		Struck	'		injury race	LIIBIIICEI	Struck on face by buffler
09/02/20		Struck		Y	Fracture - Wrist	Construction	Used hands to stop pile hitting cab of rig
16		Junck		'	Tracture - Wilst	Construction	Osca manas to stop pine mitting can of fig
10/02/20		Struck	Υ	+	Strain - Lower limb	Construction	No details
16		Junck	'		Juani - Lowel IIIID	Construction	ivo actaris
11/02/20		Tripped		Υ	Strain - Ankle	Technician	boot caught on steps when exiting the Turbine
16		Tripped		'	Strain - Alikie	TECHNICIAN	boot caught on steps when exiting the rurbine
11/02/20		Manual Handlin		Υ	Strain trunk	loinor	IP strained himself when lifting materials
11/02/20		Manual Handling		Y	Strain - trunk	Joiner	ir strained minisen when inting materials
10	1			_1			

16/02/20			Manual Handling		Υ	Laceration - finger	Construction	Trapped finger on manhole cover
16								
19/02/20			Slip		Υ	Strain - Ankle	Construction	Slipped and went over on ankle
16								
19/02/20			Struck	Υ		Strain - Foot	Construction	Foot trapped when materials moved
16								
26/02/20			Trapped		Υ	Contusion - Foot	Bricklayer	Foot trapped under excavator
16								
02/03/20			Trapped		Υ	Laceration - wrist	Engineer	IP hand trapped between drum and hoist plate
16								
03/03/20			Manual Handling		Υ	Laceration - finger	Joiner	trapped fingers between two weights
16								
09/03/20			Contact	Υ		Dislocation - Lower limb	Other	IP hit by excavartor bucket
16								
10/03/20			Struck		Υ	Head injury	Joiner	IP hit on head by roof truss
16								,
11/03/20			Fall		Υ	Fracture - Foot	Painter	Fall over 2ms - fell from roof
16								
14/03/20			Manual Handling		Υ	Strain	Construction	Hurt back while trying to unhook pile chain
16								, , ,
18/03/20			Contact	Υ		Laceration - Neck	Welder	No details
16								
21/03/20			pierced		Υ	hand injury	Other	Sprinter pierced hand
16			'			, ,		· · ·
22/03/20			Struck	Υ		Fracture - Finger	Scaffolder	Block fell on IP
16								
26/03/20			Manual Handling	Υ		Back injury	Engineer	Hurt back shovelling bitmac
16			8			,	9 33	
total	23	1	32	19	37			