

HSENI CONSTRUCTION GROUP STATISTICS


01 April 2016 – 30 June 2016


	fatalities	Major injuries (MI)	MI on	MI on	Over 3 day	3 day on private	3 day on	Dangerous
			private site	public site		site	public site	occurrence
Total	0	18			47			4
numbers								
Comparison			14	4		40	7	
private/public								


TABLE 1: numbers of reported incidents (including major injuries by type)











Date	Major	Fatals	Over 3 day	Public	Private	Injury (type)	Occupation	Comments	
04/04/20 16	Trip				Υ	Fracture - Wrist	Joiner	IP tripped on underlay	
07/04/20 16	Fall				Υ	Fracture - Upper limb	Labourer	Fall over 2ms -Fell from scaffolding	
08/04/20 16	Fall			Υ		Fracture - Upper limb	Labourer	Fall under 2ms - Fell from ramp	
11/04/20 16	Faint			Υ		Head injuries	Construction	Collapsed - no further details available	
13/04/20 16	Fall				Υ	Fracture - ankle	Scaffolder	Fall over 2ms -	
18/04/20 16	Fall				Υ	Fracture - foot	Electrician	Fall under 2ms - jumped from ladder	
28/04/20 16	Fall				Υ	Fracture - back	Painter	Fall over 2ms	
02/05/20 16	Contact				Υ	Fracture - wrist	Bricklayer	Cement mixer handle kicked back hit IP wrist	
13/05/20 16	Manual Handling				Υ	Fracture - wrist	Welder	Carrying sheet steel injured wrist	
17/05/20 16	Contact			Υ		Amputation - finger	Not Known	Came into contact with excavator	
20/05/20 16	Electric Shock				Υ	unconscious	Technician	pulling cables through a void received electric shock	
25/05/20 16	Contact			Υ		Fracture - wrist	Construction	Mixer handle slipped & injured IP	
01/06/20 16	Exposure				Υ	Burns -multiple	Construction	Took radiator cap off excavator resulting to hot water burns face and arms	
06/06/20 16	Contact				Υ	Lacerations - upper limb	Plasterer	Injured while using grinder	
06/06/20 16	Exposure				Υ	Burns - eye	Plumber	Solder dropped in eye	
07/06/20 16	Slip				Υ	Fracture - Wrist	Driver	Slipped from dumper truck	
09/06/20 16	Other				Υ	Dislocation - lower limb	Plumber	Missed step	
22/06/20 16	Strike				Υ	loss of sight	Painter	bumped head on low ceiling	
06/04/20 16			Exposure		Υ	Burns - fingers	Construction	Details not known	
08/04/20 16			Strike		Υ	Superficial injury - hand	Engineer	IP hand got stuck between wall and equipment	

08/04/20 16	Manual Handling	Υ	Strain - back	Roofer	IP hurt back while carrying broken roof tiles		
11/04/20 16	Manual Handling	Y	Strain - multiple	Plumber	Hurt neck and back while using kango hammer		
12/04/20	Manual Handling	Y	Strain - back	Builder	Gradual work causing back problems		
16							
12/04/20 16	Struck by Y		Superficial - lower limb	Admin	IP queuing when pipe in chiller burst and shrapnel hit her legs		
12/04/20 16	Manual Handling	Y	Strain - back	Electrician	IP hurt back while trying to open door of cabinet		
13/04/20	Contact	Υ	Back injuries	Drivers mate	hit his back on the leg of grab		
16	Johnson		Justinjanes	2	THE THE BOOK OF THE TEB OF BLOD		
13/04/20 16	Trip	Υ	Contusion - lower limb	Construction	tripped on uneven ground		
14/04/20	Trip	Υ	Strain - foot	Builder	lost footing & grinder fell on foot		
16	•				and the state of t		
14/04/20 16	Trip Y		Lower limb injury	Labourer	Twisted leg when getting upright		
15/04/20	Struck by	Y	Contusion - ankle	Construction	clay from trench collapsed on IP ankle		
16 18/04/20	Strike	Υ	Superficial - finger	Joiner	caught fingers while lifting floor boards		
16	Strike	Ť	Superficial - finger	Joiner	Caught inigers while litting floor boards		
19/04/20 16	Trip	Υ	Strain - lower limb	Bricklayer	tripped on scaffolding and lost footing		
19/04/20 16	Fall	Y	Contusion - lower limb	Construction	Fall under 2ms		
20/04/20	Faint	Υ	Superficial - face	Construction	IP collapsed and fell cutting face when landed		
16							
21/04/20 16	Manual Handling Y		Strain - back	Plumber	hurt back while tightening a bolt		
22/04/20	Fall	Y	Strain - multiple	Labourer	Fall under 2ms - slipped on flat roof and fell		
16 05/05/20	Manual Handling	Υ	Fracture - finger	Construction	Attach on plant, altipopal voltage ID lifeting it		
16	Manual Handling	Y	Fracture - Imger	Construction	timber plank slipped when IP lifting it		
05/05/20	Trip	Υ	Strain - foot	Construction	Tripped on loose blocks		
16	,						
05/05/20	Manual Handling	Υ	Strain - Back	Joiner	Hurt back while carrying bags of rubble		
16							
09/05/20 16	Fall	Y	Fracture - lower limb	Crane Driver	Lost balance while dismounting crane		
12/05/20	Exposure	Y	Burns - Eye	Construction	Resin came in contact with IP's eye		
16	111 111	.,,		<u> </u>			
13/05/20 16	Manual Handling	Y	Fracture - Toe	Construction	concrete pipe fell on IP toe		

Struck by		Υ	Laceration - lower limb	Labourer	Wash hand basin broke and hit ID on logs		
,		•	Laceration - lower lillin	Labourer	Wash hand basin broke and hit IP on legs		
Fall		Υ	Strain - trunk	Painter	Fall under 2ms - fell off trestles		
Strike		Υ	Dislocation - Lower limb	Construction	Kicked plywood and hurt knee		
Manual Handling		Υ	Superficial - lower limb	Construction	Scraped shin on bottom of wheelie bin		
Trip		Υ	Strain - ankle	Engineer	Went over on ankle		
Manual Handling		Υ	Strain - lower limb	Fitter	Bent down and knee popped		
Fall		Υ	Superficial - Back	Construction	lost balance while on steps		
Manual Handling	Υ		Superficial - wrist	Cleaner	cut wrist while drying cup		
Struck by	Υ		Strain - ankle	Labourer	piece of scaffold fell and hit IP		
Exposure		Υ	Superficial - eye	Construction	IP moving branches & one shot up hit him in eye		
Manual Handling		Υ	Strain - back	Construction	when rising from floor twisted back		
Manual Handling		Υ	Strain - fingers	Plasterer	IP hurt thumb while taking down stud wall		
Tranned		V	Contusion - hand	Construction	Hand caught as wrench rotated		
Парреа			Contasion nama	Construction	Traina caught as weller rotated		
Contact		Υ	Laceration -finger	Construction	Hand caught between van door and handle of rotovator		
Struck by		Υ	Fracture - ankle	Construction	brick struck IP on ankle		
Manual Handling		Υ	Strain - fingers	Plant drivers	IP finger got trapped between JCB bucket and toe		
Contact		Υ	Concussion - head	Construction	IP struck on head by excavator bucket		
Manual Handling	Υ		Fracture - Hand	Scaffolder	hit hand on standard		
Struck by		Υ	Concussion - head	Other	IP hit by crowbar		
Trip		Υ	Strain - back	Surveyor	tripped on uneven ground		
Manual Handling		Υ	Strain - back	Fitter	IP hurt back while lifting		
Contact		Υ	Superficial -lower limb	Joiner	saw kicked back and cut IP		
	Strike Manual Handling Trip Manual Handling Fall Manual Handling Struck by Exposure Manual Handling Manual Handling Trapped Contact Struck by Manual Handling Contact Struck by Manual Handling Trapped Trip Manual Handling	Strike Manual Handling Trip Manual Handling Fall Manual Handling Y Struck by Y Exposure Manual Handling Manual Handling Trapped Contact Struck by Manual Handling Contact Struck by Manual Handling Y Struck by Manual Handling Trapped Contact Struck by Manual Handling Trip Manual Handling	Strike Y Manual Handling Y Trip Y Manual Handling Y Fall Y Manual Handling Y Struck by Y Exposure Y Manual Handling Y Trapped Y Contact Y Struck by Y Manual Handling Y Struck by Y Trip Y Manual Handling Y Manual Handling Y Trapped Y Contact Y Struck by Y Manual Handling Y Manual Handling Y Contact Y Manual Handling Y Trip Y Manual Handling Y	Strike Y Dislocation - Lower limb Manual Handling Y Superficial - lower limb Trip Y Strain - ankle Manual Handling Y Strain - lower limb Fall Y Superficial - Back Manual Handling Y Strain - ankle Exposure Y Superficial - eye Manual Handling Y Strain - back Manual Handling Y Strain - fingers Trapped Y Contusion - hand Contact Y Laceration -finger Struck by Y Fracture - ankle Manual Handling Y Strain - fingers Contact Y Concussion - head Manual Handling Y Strain - fingers Contact Y Concussion - head Manual Handling Y Strain - back Manual Handling Y Strain - back	Strike Y Dislocation - Lower limb Construction Manual Handling Y Superficial - lower limb Construction Trip Y Strain - ankle Engineer Manual Handling Y Strain - lower limb Fitter Fall Y Superficial - Back Construction Manual Handling Y Superficial - wrist Cleaner Struck by Y Strain - ankle Labourer Exposure Y Superficial - eye Construction Manual Handling Y Strain - back Construction Manual Handling Y Strain - fingers Plasterer Trapped Y Contusion - hand Construction Contact Y Laceration - finger Construction Struck by Y Fracture - ankle Construction Manual Handling Y Strain - fingers Plant drivers Contact Y Concussion - head Construction Manual Handling Y Strain - fingers Plant drivers Contact Y Concussion - head Construction Manual Handling Y Strain - back Surveyor Trip Y Strain - back Surveyor Manual Handling Y Fitter		

30/06/20 16		Exposure	Υ		Unknown	Other	Potential exposure to asbestos fragments
total	18	47	11	54			