

HSENI CONSTRUCTION GROUP STATISTICS

01 Oct 2016 – 31 December 2016







3

Oct 15-Dec 15

Oct 16-Dec 16

2

| Major | Fatals | Over 3 day | Public | Private | Injury (type) | Occupation | Comments |
|--------|--------|-----------------|--------|---------|------------------------|--------------|---|
| Fall | | | | Y | Fracture - Lower Limb | Painter | Fall over 2ms - Fell from roof |
| Fall | | | Y | | Fracture – Foot | Labourer | Fall under 2ms - fell from step ladder |
| Fall | | | | Y | Fracture – Back | Construction | thrown from dumper truck |
| Fall | | | | Y | Fracture - Upper body | Fitter | Fall over 2ms - fell from roof |
| Fall | | | | Y | Fracture - Upper Limbs | Not Known | Fall over 2ms - Fell from scaffold |
| Fall | | | | Y | Fracture – Wrist | Construction | Fall over 2ms - Fell from scaffold |
| Struck | | | | Y | Fracture – Hand | Technician | Hand got caught underneath floor plate |
| Fall | | | Y | | Fracture – Wrist | Construction | Fall under 2ms - fell getting out of van |
| Trip | | | Y | | Fracture – Wrist | Construction | Tripped over electric cables |
| Struck | | | | Y | Fracture - Lower Limbs | Construction | Wooden joists fell on IP |
| Trip | | | Y | | Fracture – Face | Construction | Tripped on liner and fell |
| Fall | | | | Y | Fracture – Wrist | Construction | Fall under 2ms - fell from joiners stool |
| Struck | | | | Y | Neck injuries | Scaffolder | Hit on hard hat by piece of wood accidentally dropped from area above |
| Struck | | | | Y | Fracture – Foot | Fitter | Digger bucket rolled on to IP foot |
| Trip | | | Y | | Fracture – Ankle | Construction | Lost footing and tripped |
| Fall | | | | Y | Fracture – Face | Roofer | Fall over 2ms - Fell from scaffold |
| Fall | | | | Y | Fracture – Trunk | Joiner | Fall under 2ms - fell from wall pan |
| Fall | | | | Y | fracture – Multiply | Plasterer | Fall over 2ms - fell from ladder |
| Fall | | | Y | | Fracture – Wrist | Joiner | Fall under 2ms - Fell off toolbox |
| Fall | | | | Y | Fracture – Foot | Roofer | Fall over 2ms - Fell through roof |
| Fall | | | | Y | Fracture – Trunk | Construction | Fall under 2ms - Fell while pushing wheel barrow |
| Slip | | | Y | | Dislocated -Upper limb | Plasterer | Slipped while walking through hallway and fell over |
| Struck | | | | Y | fracture – Foot | Construction | |
| Slip | | | | Y | Fracture - Upper Limbs | Construction | Slipped on step and fell over |
| Struck | | | | Y | Fracture - Upper body | Construction | steps collapsed and fell on IP |
| | | Manual Handling | | Y | Strain - Lower Limb | Plumber | IP stretching to reach and felt pain in his back |
| | | Manual Handling | | Y | Strain – back | Construction | pushing excessively and caused back pain |
| | | Slip | | Y | Strain - Lower Limb | Other | Slipped on grass |
| | | Struck | | Y | Fracture – Hand | Technician | Handed got wedged between a load |

| | | | 1 | | | |
|----|------------------|---|---|---------------------------|--------------|--|
| ļ | Fall | | Y | Strain - Lower Limb | Cleaner | Fall under 2ms - Fell into a drain |
| | Cut | Y | | Laceration – Hand | Bricklayer | cut his hand with Stanley knife |
| | Manual Handling | | Y | Laceration – Hand | Roofer | IP caught hand on hook |
| | Struck | | Y | Contusion – back | Roofer | Struck by MEWP |
| | Fall | | Y | Superficial injuries | Plasterer | Fall under 2ms - fell from scaffold |
| | Strike | | Y | Injured – finger | Construction | Hit finger off ladders |
| | Struck | | Y | Superficial injuries | Construction | struck right side on trusses |
| | Manual Handling | Y | | Strain – Back | Other | Lifting bag of sand and hurt back |
| | Electric contact | | Y | Loss of consciousness | Electrician | Electric shock when working with faulty cable |
| | Struck | | Y | Laceration – Head | Construction | IP thrown on widow of vehicle when it capsized |
| | Manual Handling | | Y | Dislocation – Finger | Technician | Pushing crowbar and hands slipped |
| | Trip | | Y | Superficial - Lower Limbs | Construction | Tripped on manhole cover |
| | Fall | Y | | Dislocation - Upper Limb | Joiner | Fall over 2ms - Fell from scaffolding |
| | Slip | | Y | Laceration - Lower Limb | Other | Slipped on sewage pipe fell over |
| | Manual Handling | | Y | Laceration – Finger | Fitter | Nipped finger on Diverter |
| | Contact | | Y | Laceration – Finger | Construction | caught finger on chain of cement mixer |
| | Other | | Y | Upper Limb injuries | Engineer | |
| | Fall | Y | | Fracture – Multiply | Construction | Fall over 2ms - Fell from roof |
| | Fall | | Y | Wrist injury | Construction | Fall over 2ms - slipped from ladders |
| | Other | | Y | Superficial – Eye | Labourer | Dust in eye causing irritation |
| | Struck | Y | | Contusion – Neck | Bricklayer | IP struck on head by telehandler |
| | Fall | Y | | Strain – Ankle | Construction | Fall over 2ms - scaffold plank broke IP fell |
| | Other | Y | | Fracture – Finger | Builder | Door closed on hand |
| | Struck | | Y | Laceration - Hand | Labourer | Cut hand when removing tiles |
| | Struck | | Y | Fracture - Finger | Construction | Fingers hit by hammer |
| | Manual Handling | | Y | Strain - Back | Labourer | Hurt back when moving container |
| | | | | | | |
| 25 | 30 | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| , | | 1 | | | 1 | |